


SpanSet secutex®

02

Lifting
Buffer pad
Lifting equipment





For careful coil handling and safe storage.

A significant proportion of a product's total costs are attributable to damage resulting from a lack of buffer pad. The principal causes are carelessness, negligence and improper handling. This represents avoidable damage to goods and stock.

secutec Coilprotect is the optimum solution for the safe handling, efficient transport and careful storage of coils and wire coils.

At the processing plants, the coils must be placed in an upright position ready for machining. Serious workplace accidents occur again and again due to coils toppling over.

Of increasing importance is the protection of metal coils produced or intended for further processing. Improper handling and incorrect storage are the most frequent causes of dents in delicate metal sheet coils. These, in turn, can lead to considerable problems during later forming. „Renowned car manufacturers had discovered

that dents can be detected through to the sixth layer. This gives rise to considerable problems and additional costs during the forming process.“ secutex, a polyurethane elastomer with excellent physical and chemical properties, can be moulded into just about any shape:

High structural strength

Compared with other chemical materials, secutex is extremely tear-resistant. The polyurethane can be stretched to 500% of its original length without breaking.

High flexibility

secutex offers considerably greater flexibility in comparison to conventional rubber - even with extreme temperature fluctuations.

Extreme wear and abrasion resistance

secutex is virtually indestructible. In wet wear resistance tests, secutex performed better than many metals.

02.2 COILPROTECT

secutex floor plates
secutex turning mat

Slip-resistant and protective underlays

secutex floor plates



Slip-resistant and protective

Often freshly-wound coils are temporarily stored on cardboard or felt. With oily coils, the cardboard or felt absorb the oil and must be disposed of at expense as hazardous waste.

secutex floor plates (right) can be rapidly cleaned of oil and dirt residues. Even in the case of heavy and long-term use, the extreme cut resistance and pressure resistance prevents the penetration of dirt particles into the surface. Thanks to the surrounding ramp, the floor plate can be driven over without any problem.

Available as an option

- Surface structures (profiling etc.)
- secutex heat (heat-resistant buffer pad)
- Individual warnings and markings



secutex turning mat

Careful and controlled turning

When rolling off a load over the floor, the heavy load can slip uncontrollably on the smooth warehouse floor. There is considerable risk of accidents. Expensive workpieces can be damaged under their own weight and may require time-consuming reprocessing. secutex turning mats (see figure above) are completely slip-resistant. The turning manoeuvre can be performed safely and smoothly.

Available as an option

- Surface structures (profiling etc.)
- secutex heat (heat-resistant buffer pad)
- Individual warnings and markings

www.secutex.com

Technische Änderungen vorbehalten. Alle Rechte vorbehalten. Kein Teil des Katalogs darf in irgendeiner Form (Druck, Fotokopie, oder ein anderes Verfahren) ohne schriftliche Genehmigung reproduziert oder unter Verwendung elektronischer Systeme verarbeitet, vervielfältigt oder verbreitet werden. Der vorliegende Katalog wurde mit der gebotenen Sorgfalt erarbeitet.

SpanSet secutex Sicherheitstechnik GmbH
übernimmt keinerlei Haftung für Fehler oder Auslassungen.

**SpanSet-secutex
Sicherheitstechnik GmbH**

Am Forsthaus 33

52511 Geilenkirchen

Germany

Tel +49 (0)24 51 48 45 73-0

Fax +49 (0)24 51 48 45 73-119

info@secutex.de

www.secutex.de

Ihre SpanSet-secutex-Werkvertretung